


Index No. C 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5th Coordinates: X _____ Y _____
E 1/4 4 Corner common to sections 3, 4



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1871
Original monument POST

Year of search _____ By _____
Monument found _____

Species	Bearing	Tree	Distance
<u>SPRUCE</u>	<u>N 1/2° E</u>	<u>TRUSS</u>	
<u>10"</u>	<u>8"</u>		
<u>54° E</u>	<u>57° W</u>		
<u>13 LKS</u>	<u>21 LKS.</u>		

Species	Bearing	Tree	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1936 By Roger Mustonen
Location filed Corner Certificate - Doc # 295216
Monument set 2" USES l.p. w/brass cap et Siley
edge power line - 1 1/2 x 48" l.p. found on ground.
Corner set at single proportion location

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species	Bearing	Tree	Reference Objects	Distance
<u>Maple</u>	<u>8"</u>	<u>Balsam</u>	<u>Balsam</u>	
<u>11"</u>	<u>9"</u>			
<u>N 14 1/2° W</u>	<u>56 1/2° E</u>	<u>55 1/2° W</u>		
<u>56.32'</u>	<u>25.67'</u>	<u>19.75'</u>		

Species	Bearing	Tree	Reference Objects	Distance
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____
Certificate - Roger Mustonen - 1987

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____