


Index No. DE 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 12 Corner common to sections \_\_\_\_\_



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Bearing Trees	
Species <u>SPRUCE</u>	<u>FIR</u>
Diameter <u>6"</u>	<u>8"</u>
Bearing <u>S50W</u>	<u>S37E</u>
Distance <u>8 LKS</u>	<u>14 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1987 By Roger Mustonen  
Location filed Corner Certificate - Doc # 295217  
Monument End remains of GLO B.T. - and part of post. set 2" x 36" sq telescope monument w/ aluminum cap

Bearing Trees, Reference Objects		
Species <u>Tam.</u>	<u>Balsam</u>	<u>Survey marker</u>
Diameter <u>8"</u>	<u>4"</u>	<u>sign</u>
Bearing <u>N63 1/2° E</u>	<u>S63 1/2° E</u>	<u>west</u>
Distance <u>8.88'</u>	<u>18.20'</u>	<u>1'</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Roger Mustonen - 1987

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_