Index No. E 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____

NE 9 Corner common to sections 3, 4, 9, 10



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	BIRCH	LINDEN	ELM	MAPLE
Diameter	10"	10"	6"	8"
Bearing	S20W	S54E	N76E	N18W
Distance	58 LKS	44 LKS	17 LKS	39 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1986 By Roger Mustonen

Location filed Corner Certificate - Doc# 295220

Monument Fnd 1" iron rod 21" long - replaced with 2" USFS l.p. w/ brass cap in ℄ old E-W ditched road, 397' W. of ℄ USFS Rd # 2069

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Poplar	Red oak	Poplar	Poplar
Diameter	5"	14"	5"	5"
Bearing	N48½W	N57½°E	S20½°E	S31½°W
Distance	29.42'	53.66'	25.45'	28.51'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Roger Mustonen - 1987

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____