


Index No. J 19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 14 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species	<u>ASPEN SPRUCE</u>
Diameter	<u>20" 18"</u>
Bearing	<u>S 74 W N 47 W</u>
Distance	<u>13 LKS 3 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By JAMES FLYNN
Location filed COUNTY SURVEY "E-7"
Monument IRON MONUMENT
1920, J. FLYNN, BOOK "C" P. 383 SET 1/2 x 48" I.M. PROVISIONAL

Evidence of Subsequent Corner Restoration

Year of search 2/1940 By R.T. DeFant
Ed. iron pipe, in fence line, leans west.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Poplar</u>	_____	_____
Diameter	<u>3"</u>	_____	_____
Bearing	<u>South</u>	_____	_____
Distance	<u>9 lks</u>	_____	_____
	<u>12.54'</u>	_____	_____

J-19

Subsequent Corner Restoration

Year surveyed 1/1982 By R. Oleson USFS
Location filed USFS Cass Lake
Monument Found Nothing.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

11/2002 R. Main USFS, found fence corner, DeFant tag.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____