


Index No. L17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E1415 Corner common to sections 14,15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>	_____
Diameter	<u>8"</u>	<u>12"</u>	_____
Bearing	<u>S60W</u>	<u>S72E</u>	_____
Distance	<u>24LKS</u>	<u>19LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By JAMES FLYNN  
Location filed COUNTY SURVEY "E-1"  
Monument IRON MONUMENT  
1920 J. FLYNN, COUNTY BOOK 8' P. 384 SET 1/2" x 48" I.M.

Evidence of Subsequent Corner Restoration

Year of search 11/95 By C. Krause USFS  
Ed 2" x 48" iron pipe, in swamp. Drove  
8' steel post at south edge of iron  
and wired together.

Bearing Trees, Reference Objects

Species	<u>TAM</u>	<u>TAM. SUB</u>	_____
Diameter	<u>6"</u>	<u>7"</u>	_____
Bearing	<u>S74E</u>	<u>N16W</u>	_____
Distance	<u>56.5'</u>	<u>36.2'</u>	_____

Bearing Trees, Reference Objects

<u>Sign Post</u>	<u>Sign Post</u>	<u>Sign Post</u>
<u>8'</u>	<u>8'</u>	<u>8'</u>
<u>South</u>	<u>East</u>	<u>N 45° W</u>
<u>4.2'</u>	<u>4.5'</u>	<u>4.5'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_