


Index No. C3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
C/4 Corner common to sections 6



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
Original monument 1x36" I.P. W/BRASS CAP C/4 S6 1919

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species N. Pine BL. OAK
Diameter 10" 22"
Bearing N18°E S8E
Distance 76 LKS 165 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed 2/78 By USFS, Sirlbaugh
Location filed USFS Cass Lake, BK1, pg 58
Monument Found 1" iron & cap, 10" above ground

Evidence of Subsequent Corner Restoration

Year of search 10/81 By USFS, Ausk
Found monument, steel sign post
West 2.5 & South 4.15, line to standard South & West.

Bearing Trees, Reference Objects

Species N. Pine
Diameter stump
Bearing N18°E
Distance 50.2'

Bearing Trees, Reference Objects

W. Oak W. Oak W. Oak
6" 6" 8"
S48°E S57°W N67°W
40.94' 25.29' 39.62'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____