


Index No. E3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
N¹/₄ 7 Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. PINE
Diameter 30"
Bearing S 72 E
Distance 13 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed SECRETARY OF STATE
Monument NO EVIDENCE OF ORIGINAL SET 1876
I.P. W/ BRASS CAP
114 56
57
1919

Evidence of Subsequent Corner Restoration

Year of search 3/86 By USFS, Krause
Area was dozed for fence, Bca E
dist from oak falls 2' East of
fence. Need traverse to reset.

Bearing Trees, Reference Objects

Species PAVIA W. OAK
Diameter 6" 12"
Bearing N 7-30 E S 36 W
Distance 141 LKS 184 LKS

Bearing Trees, Reference Objects

GLO Oak
17"
S 36 W
121.44

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____