


Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 8 Corner common to sections 4, 5, 8, 9



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	CEDAR	CEDAR	FIR	FIR
Diameter	5"	6"	5"	6"
Bearing	S48W	N30W	N50E	S47E
Distance	4 LKS	8 LKS	10 LKS	9 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLO  
Location filed SECRETARY OF STATE  
Monument END OLD GOVT BITS: CEDAR 12" N30W 8 LKS,  
12" CEDAR S 48 W 4 LKS. SET 1X36" I.P. W/BASS CAP

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

TWIN RTW  
55 | 54

Bearing Trees, Reference Objects

Species	CEDAR	CEDAR	BTIM GILEAD
Diameter	5"	8"	12"
Bearing	S19-45E	S51-15W	N40-15W
Distance	33 LKS	19 LKS	84 LKS

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_