


Index No. J 2-3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

MC Corner common to sections 7, 18

NOT ORIGINAL



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 T141N  
Original monument 1x36" I.P. W/BRASS 57 / M.C.  
CAP R27W

Bearing Trees

Species	<u>W. PINE</u>	<u>POPULAR</u>	
Diameter	<u>15"</u>	<u>15"</u>	
Bearing	<u>N46W</u>	<u>S82-45W</u>	
Distance	<u>23 LKS</u>	<u>97 LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 9/69 By USFS, #6807  
Location filed USFS Cass Lake BL 1, pg 31  
Monument Monument gone set 6"x24"  
Concrete w/Brass cap from GLO  
Witness trees (overgrown)

Bearing Trees, Reference Objects

Species	<u>W. Pine</u>	<u>W. Pine</u>	<u>R. Oak</u>
Diameter	<u>20"</u>	<u>27"</u>	<u>10"</u>
Bearing	<u>N32°E</u>	<u>N8°E</u>	<u>N48°W</u>
Distance	<u>56.7'</u>	<u>53.9'</u>	<u>16.1'</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration 2-3

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL C. KERMANN - 1969  
Set 6"x24" concrete monument with 3"  
marked brass tablet. Ties: 20" W. Pine  
N32E 56.7'; 27" W. Pine N8E 54.13';  
10" B. Oak N48W 16.1'.

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_