


Index No. M3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.S. 116 Corner common to sections 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919  
Original monument 1x36" I.P. w/BRASS CAP S 116 & S 18  
C  
1919

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>POPULAR</u>	<u>POPULAR</u>	_____
Diameter	<u>12"</u>	<u>8"</u>	_____
Bearing	<u>N85-15E</u>	<u>S11-30W</u>	_____
Distance	<u>161 LKS</u>	<u>258 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 9/80 By USFS, Krause  
Location filed USFS Cess Lake, BK. 3, Pg 28  
Monument Found iron & cap, bent, in woods trail, FSLP on witness

Evidence of Subsequent Corner Restoration

Year of search 8/81 By USFS, Krause  
Set 2"x36" iron pipe with brass cap, place GLO monument on N. side.

Bearing Trees, Reference Objects

Species	<u>R. Oak</u>	_____	_____
Diameter	<u>10"</u>	_____	_____
Bearing	<u>N53°E</u>	_____	_____
Distance	<u>11.25'</u>	_____	_____

Bearing Trees, Reference Objects

<u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>	<u>Cedar Post</u>
<u>10"</u>	<u>8"</u>	<u>9"</u>	<u>4x4"</u>
<u>N66°E</u>	<u>S40°E</u>	<u>S52°W</u>	<u>N78°W</u>
<u>22.57'</u>	<u>31.65'</u>	<u>20.91'</u>	<u>12.72'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_