Index No. N21-22

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____

MC # 3 Corner common to sections 13, 24




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1874

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | W. Pine | Basswood | | |
| Diameter | 10" | 6" | | |
| Bearing | S70W | N58W | | |
| Distance | 33 Lks | 14 Lks | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed AUGUST 1937 By J.A. GIELHAUG - CCC

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | OREGN. PINE | | | |
| Diameter | 12" BT | | | |
| Bearing | S50°W | | | |
| Distance | 10 lks | | | |

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____