


Index No. N3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 574 Coordinates: X _____ Y _____
N1419 Corner common to sections 18, 19



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter NO TREES.
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed SEC. OF STATE
Monument PROPORTIONAL LOCATION - UNABLE TO FIND ORIGINAL POST SET 1X 36" IRON POST W/ BRASS CAP.

Evidence of Subsequent Corner Restoration

Year of search 1922 By J.H. FLYNN
COUNTY BOOK D' P. 75 FND CUT IRON CORNER.

1982 - Gary Stevenson - Corner Certificate in 1980 - P. Krause USFS Fnd Brass cap and remains of both 1919 B.T.S'

Bearing Trees, Reference Objects 1919

Species W. OAK N. PINE
Diameter 70" 8"
Bearing S 77-45E S 10-45W
Distance 162 LKS 300 LKS.

Bearing Trees, Reference Objects

<u>W. oak</u>	<u>W. oak</u>	<u>W. oak</u>
<u>7"</u>	<u>11"</u>	<u>7"</u>
<u>N74E</u>	<u>S82E</u>	<u>S11E</u>
<u>66.7'</u>	<u>112.7'</u>	<u>82.2'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - Filed by USFS 1984
Doc. # 279273 dated 1982

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____