


Index No. 05

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
W.C. N 1/4 Corner common to sections 19, 20 W.C. 4, 12 CH. SOUTH



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 W.C. N 1/4
Original monument 1 X 3/8" Iron Post 519/520
W/BRASS CAP 1919

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species POPULAR POPULAR _____
Diameter 8" 12" _____
Bearing S 36-15E S 53-15W _____
Distance 62 LKS. 90 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1982 By Gary Stevenson
Location filed Corner Certificate
Monument In 1980 USES find brass cap leaning south
and rotted stump SE & depression SW

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species w. pine w. oak N. pine
Diameter 31" 11" 21"
Bearing S 68E S 29E S 61W
Distance 73.4' 49.0' 79.6'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - filed by USES
Doc # 879278 1984 - dated 1982

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____