


Index No. 06-7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E-Nw 1/64 Corner common to sections 20



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1919

Original monument K36" I.P. w/BRASS CAP

Bearing Trees

Species _____	Diameter _____	Bearing _____	Distance _____
---------------	----------------	---------------	----------------

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	Diameter _____	Bearing _____	Distance _____
---------------	----------------	---------------	----------------

**Subsequent Corner Restoration**

Year surveyed 1982 By Gary Stevenson

Location filed Corner Certificate

Monument in 1980-1981 - USFS find brass cap - dist check good - also bearings to other corner

Bearing Trees Reference Objects

Species <u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>19"</u>	<u>15"</u>	<u>18"</u>
Bearing <u>N37E</u>	<u>S7W</u>	<u>N18W</u>
Distance <u>28.9'</u>	<u>3.85'</u>	<u>6.9'</u>

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species _____	Diameter _____	Bearing _____	Distance _____
---------------	----------------	---------------	----------------

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Gary Stevenson - filed by USFS  
Doc. # 279334 1984 - dated 1982

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_