


Index No. R13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 28 Corner common to sections 21, 22, 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>Spruce</u>	<u>TAM</u>	
Diameter <u>6"</u>	<u>7"</u>	
Bearing <u>S39E</u>	<u>S30W</u>	
Distance <u>27LKS</u>	<u>23LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1994 3-4 By Terry Freeman  
Placed 3" x 24" iron pipe w/ brass cap over 8' steel sign post, up 20"  
5-4-94 CER. Filed by Terry Freeman, RLS 21367, Doc. # 357305.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Bl. Spruce	Bl. Spruce	Bl. Spruce	Bl. Spruce
<u>5'12"</u>	<u>5'12"</u>	<u>5"</u>	<u>5"</u>
<u>N40W</u>	<u>S65W</u>	<u>S7E</u>	<u>N75E</u>
<u>20.12'</u>	<u>6.37'</u>	<u>15.66'</u>	<u>17.60'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_