


Index No. R15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
N1/4 27 Corner common to sections 22, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>N. PINE</u>	<u>N. PINE</u>	
<u>18"</u>	<u>20"</u>	
<u>N8W</u>	<u>54W</u>	
<u>85 LKS</u>	<u>78 LKS</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1920 By LINCOLN MACKET
Location filed COUNTY BOOK "C" P. 379
Monument FIND CORNER AND GALT B.T.S.

Evidence of Subsequent Corner Restoration

Year of search 1993 12-11 By Terry Freeman
Found 2" x 5' galvanized steel pipe filled with concrete & capped w/ a 3" stamped brass tablet. Left as found.
5-4-94 Cert. Filed by Terry Freeman, R15 21367, Doc. # 357306

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects	White Oak	White Oak	White Oak
<u>Pine Stump (orig)</u>	<u>8"</u>	<u>6 1/2"</u>	<u>16"</u>
<u>N8W</u>	<u>N19W</u>	<u>N82W</u>	<u>S22W</u>
<u>56.1</u>	<u>28.20</u>	<u>27.20</u>	<u>29.00</u>
	<u>(ALB USFS BT)</u>	<u>(ALB USFS BT)</u>	<u>(ALB USFS BT)</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969
Found burned stump for 18" N. Pine N8W 56.1'; found burned stump for 20" N. Pine 54W 51.5'.
set 2" x 5' galvanized steel pipe filled with concrete and capped with 3" stamped brass tablet. Ties: 14" W. Oak S22W 29.0'; 5" W. Oak N82W 27.2'; 6" W. Oak N19W 28.9'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____