


Index No. R19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
N14 26 Corner common to sections 23, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument POST

Bearing Trees

Species	<u>CEDAR</u>	_____	_____
Diameter	<u>6"</u>	_____	_____
Bearing	<u>N70E</u>	_____	_____
Distance	<u>40 LB.</u>	_____	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1994 3-4 By Terry Freeman

Placed a 2" x 24" iron pipe w/ brass cap over 8' steel sign post, up 19"

5-4-94 Cert. Filed by Terry Freeman, RLS 21367, Doc. # 357308.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>White Pine</u>	<u>Black Spruce</u>	<u>Black Spruce</u>
<u>15"</u>	<u>6"</u>	<u>5"</u>
<u>N51 E</u>	<u>S70 W</u>	<u>S46 E</u>
<u>27.33'</u>	<u>10.93</u>	<u>28.25</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____