


T. 141 R. 27 M. 5th Coordinates: X NE 25 Corner common to sections 24, 25 and 19, 30-141-26 Y _____



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument Post

Species	Bearing	Trees
<u>SPRUCE</u>	<u>SPRUCE</u>	<u>BIRCH</u>
Diameter <u>12"</u>	<u>14"</u>	<u>4"</u>
Bearing <u>N46E</u>	<u>51W</u>	<u>550E</u>
Distance <u>10LKS</u>	<u>40LKS</u>	<u>20LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By J.H. FLYNN

Location filed COUNTY BOOK "B" P.510-511

Monument FND OLD GOVT PITS: 12" SPRUCE N46E 10 LKS, 14" SPRUCE 51W 84 LKS, 4" BIRCH 550E 20 LKS. SET POST 1920, LINCOLN MARKET, BOOK "C" P.370 FND 6"x6"x36" wood post

Evidence of Subsequent Corner Restoration

Year of search 1937 By R.T. Defant (CCC)

Found iron pipe & Scribe Square post.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>TAM.</u>	<u>7"</u>	<u>N17W</u>	<u>25.5'</u>
<u>TAM</u>	<u>8"</u>	<u>537E</u>	<u>36'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Aspen</u>	<u>9"</u>	<u>N15°W</u>	<u>11LKS (7.3')</u>
<u>Aspen</u>	<u>12"</u>	<u>S72°E</u>	<u>29LKS (19.1')</u>

R-25

Subsequent Corner Restoration

Year surveyed 11/67 By L. Elliott (USFS)

Location filed USFS Cass Lake

Monument Found FSLP on 9" Balsam

8/77 - M. Stefan, USFS found 1 1/8" Axel along side post point and remains of GLO & 1912 witnesses, replace axel with 2 1/2" x 5' galv iron pipe/Brass Cap and witnesses!

7" Spruce N48°E, 64.17'

8" Spruce S23°E, 52.36'

12" Cedar S76°W, 97.24'

8" Spruce N30°W, 63.74'

Sign Post East, 2.5'

9/03 - R. Main, USFS found monument 515'± West of FR 2103, 1977 Cedar only remaining witness.

DGPS 47°00'23.73312", 94°01'44.51021"

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____