


Index No. T 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 574 Coordinates: X _____ Y _____
E 1/4 26 Corner common to sections 25, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>CEDAR</u>	<u>CEDAR</u>	_____	_____
Diameter	<u>6"</u>	<u>8"</u>	_____	_____
Bearing	<u>EAST</u>	<u>N75W</u>	_____	_____
Distance	<u>25 LKS</u>	<u>30 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1994 3-3 by Terry Freeman
Placed 2" x 24" iron pipe w/ brass cap up 20" over
8" steel sign post. 5-4-94 Cert. Filed by Terry
Freeman, RLS 21367, DOC #357312

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Black Spruce</u>	<u>Cedar</u>	<u>Cedar</u>	_____	_____
<u>6"</u>	<u>7"</u>	<u>8"</u>	_____	_____
<u>N75W</u>	<u>S56W</u>	<u>S20E</u>	_____	_____
<u>18.06</u>	<u>8.97</u>	<u>9.80</u>	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____