


Index No. X 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 33 Corner common to sections 33, 34



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1874  
Original monument Post

**Bearing Trees**

Species DEAD CEDAR  
Diameter 8"  
Bearing N30W  
Distance 23 LKS

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed 1974-1978 By M. L. STEFAN  
Location filed PLAT OF SURVEY "E-72"  
Monument 2" x 5" GALV I.P. W/ BRASS CAP. PROPORTIONED

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>R. PINE</u>	<u>R. PINE</u>	<u>R. PINE</u>	<u>STEEL SIGN POST'S</u>
Diameter	<u>19"</u>	<u>18"</u>	<u>21"</u>	<u>EAST WEST</u>
Bearing	<u>N66E</u>	<u>S80E</u>	<u>S76E</u>	<u>4.3' 2.0'</u>
Distance	<u>82.0'</u>	<u>54.2'</u>	<u>47.0'</u>	

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_