


T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
51435 Corner common to sections 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Y. PINE W. PINE
Diameter 14" 13"
Bearing N42W N4E
Distance 59 LKS 59 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1913 By HARRY S. TARD
Location filed COUNTY SURVEY RECORD BOOK 'A' P 568-570
Monument FOUND OLD GOVT B.T. 14" Y. PINE N42W 38.94'
AND STUMP 13" W. PINE N4E 38.94' SET 4"x4" PINE
STAKE

Evidence of Subsequent Corner Restoration

Year of search 1977 By DNR-Engineering
preliminary certificate in file
DNR Found 1 1/4" i.p. that USFS also found
- pipe checks with remains of 1913 ties
4 new trees taken - (not given)

Bearing Trees, Reference Objects

Species N.W. B.T. N.E. B.T. N. PINE
Diameter OLD MARK STUMP
Bearing N41-15W N4W N37-52E
Distance 38.94' 38.94' 62.25'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1993 11-23 By Terry Freeman
Found 1 1/4" iron pipe. Removed. 12-14-93 placed
5"x48" flanged iron pipe w/brass cap. 5-4-94
Cert. Filed by Terry Freeman, RLS 21367, Doc.
#357321. Ties: 15" Norway Pine N13E 90.20';
14" Norway Pine S70W 9.77' (1977 DNR BT); 15" Norway
Pine N79E 116.32' (1977 DNR BT).