


T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 23 Corner common to sections 3 AND 34-142-28



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1873  
Original monument bst  
Species OPPLAR Bearing N 1/2 Trees \_\_\_\_\_  
Diameter 12" \_\_\_\_\_  
Bearing S 1/2 W WEST  
Distance 100 LKS 12 LKS

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_  
Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1921 By GLO  
Location filed SECRETARY OF STATE  
Monument NO ORIG. EVIDENCE - SET 1x36" 1 1/2" W/  
BRASS CAP T 1/2 N  
R 28 W 534 MC  
53  
7 1/2 IN  
Bearing Trees, Reference Objects 1921  
Species R. OAK R. OAK CORNER IS  
Diameter 8" 10" 15 LKS FROM  
Bearing N 62 1/4 W S 60 3/4 E EDGE OF MARSH  
Distance 75 LKS 23 LKS

Evidence of Subsequent Corner Restoration  
Year of search 1959 By DNR-Engineering  
Map & notes in file  
Found brass cap monument  
Bearing Trees, Reference Objects  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_