


Index No. A 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
E 116 Corner common to sections 1 and 2 36-142-28



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1919
Original monument 1x36" I.P.W/BRASS CAP E 116 536
51

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species TAM. TAM. _____
Diameter 8" 5" _____
Bearing N49 1/2 E S31 3/4 E _____
Distance 41 LKS 22 LKS _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1987 By Walt Curo
Corner Certificate - Doc # 301668
Found brass cap monument in place and 1973 NW
BT.

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>Balsam</u>	<u>Balsam</u>	<u>Basswood</u>	<u>Cedar</u>
<u>15"</u>	<u>12"</u>	<u>8"</u>	<u>20"</u>
<u>EAST</u>	<u>S22 W</u>	<u>N78 W</u>	<u>N57 W</u>
<u>24.90'</u>	<u>13.30'</u>	<u>25.65'</u>	<u>42.9'</u>

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973
Certificate - Walt Curo - 1987

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____