


Index No. C 16-17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____


SMC on Corner common to sections _____
E-W 1/4 LINE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1921
Original monument 1x36" I.P. W/BRASS CAP



Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>POPLAR</u>	<u>POPLAR</u>	
Diameter <u>8"</u>	<u>6"</u>	
Bearing <u>S80 1/2 W</u>	<u>N79 1/2 W</u>	
Distance <u>61 LKS</u>	<u>86 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>OAK</u>	<u>6"</u>	<u>S9 W</u>	<u>65.40'</u>
<u>OAK</u>	<u>9"</u>	<u>S57 W</u>	<u>19.10'</u>
<u>Elm</u>	<u>5"</u>	<u>N69 E</u>	<u>49.80'</u>

C-16, 17

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972

1997 - MN/DOT found GLO Brass cap and 14' S of Twp road and witnessed:
10" Birch, West, 17.90' *
10" Birch, S40°W, 30.73' *
Steel Sign Post, South, 1.0'
* distance to copper nail and disk.

1999 - Certificate filed as #410191
by James Kramer RLS #23668 on the
1997 info.

Re monumentation certificate prepared _____ By _____

Filed at _____ Date _____