


Index No. DD

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SW 1/4 Corner common to sections 6



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36' h.p. w/BRASS CAP SW 1/4 S6 1918

Species	Bearing	Trees
<u>N. PINE</u>	<u>APPROX</u>	
<u>6"</u>	<u>10"</u>	
<u>N61/2E</u>	<u>S45W</u>	
<u>25 LKS</u>	<u>7 LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
<u>20"</u>	<u>11"</u>	<u>14"</u>
<u>N62E</u>	<u>S56E</u>	<u>S32E</u>
<u>17.50'</u>	<u>65.40'</u>	<u>90.70'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1972

Remuneration certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_