


Index No. F 12-13

CASS COUNTY LAND CORNER RECORD

T. 741 R. 28 M. 5TH Coordinates: X _____ Y _____
E-NE 1/64 Corner common to sections 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1 X 36" 1. Pin / Brass
CAP

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1971 By William Okerman

Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>Oak</u>	<u>Oak</u>	<u>Elm</u>
<u>6"</u>	<u>10"</u>	<u>7"</u>
<u>N45W</u>	<u>N41E</u>	<u>S59E</u>
<u>8.10'</u>	<u>56.50'</u>	<u>16.00'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____