


Index No. F 18-19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
E-NW 1/64 Corner common to sections 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1x36" h.p.w/brass
CAP

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

511
TR
1498
AP4
API
TR
1630
1918

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>7"</u>	<u>6"</u>	<u>8"</u>
<u>N 30 W</u>	<u>N 12 W</u>	<u>N 80 E</u>
<u>24.00'</u>	<u>18.40'</u>	<u>21.60'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Re monumentation certificate prepared _____

Filed at _____

By _____

Date _____