


Index No. G 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 11 Corner common to sections 11, 12



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1874

Original monument POST

**Bearing Trees**

Species	<u>W. PINE</u>	<u>W. PINE</u>
Diameter	<u>30"</u>	<u>24"</u>
Bearing	<u>N35W</u>	<u>N84E</u>
Distance	<u>75 LKS</u>	<u>47 LKS</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1918 By GLD

Location filed SECRETARY OF STATE

Monument PROPORTIONAL RESTORATION - NO ORIG. EVIDENCE  
SET 1x36" I.P. W/ BRASS CAP 14  
511 512  
1918

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>P. OAK</u>	<u>BL. OAK</u>
Diameter	<u>14"</u>	<u>20"</u>
Bearing	<u>N53 1/2 E</u>	<u>N12W</u>
Distance	<u>459 LKS</u>	<u>399 LKS</u>

**Bearing Trees, Reference Objects**

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - WALT CURT - 1981  
Doc. # 260873

Certificate by David Landecker 1992  
Doc # 334680  
Found 1" iron pipe with brass cap up 12".  
Ties: 1 1/2" Burr Oak N15W 34.50'; 1 1/2" Burr Oak  
N40E 20.10'; Red Oak N53 1/2 E 302.94'  
7" Burr Oak S65W 33.30'.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_