


Index No. J 17-18

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5H Coordinates: X _____ Y _____
W-W 1/64 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument N 36' 1/4 P. w/ BEASS
Bearing Trees
Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____
Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1971 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Oak Oak Elm
Diameter 8" 8" 9"
Bearing N 56 E N 59 W N 64 W
Distance 38.9' 26.3' 15.9'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____