


Index No. L 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
14 17 Corner common to sections 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument POST

Species	Bearing	Trees
<u>POPULAR</u>	<u>BIRCH</u>	
Diameter <u>6"</u>	<u>12"</u>	
Bearing <u>N49E</u>	<u>N19W</u>	
Distance <u>23 LKs</u>	<u>45 LKs</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLD

Location filed SECRETARY OF STATE

Monument PROPORTIONAL POSITION SET 1x36" I.P.W./BRASS CAP
14
517/516
1918

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman

Set 2" x 60" galvanized steel pipe with brass cap.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. PINE</u>	<u>8"</u>	<u>N23 1/2 E</u>	<u>135 LKs</u>
<u>J. PINE</u>	<u>8"</u>	<u>N62 W</u>	<u>250 LKs</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>OAK</u>	<u>4"</u>	<u>N40 W</u>	<u>16.20'</u>
<u>OAK</u>	<u>9"</u>	<u>N15 E</u>	<u>76.60'</u>
<u>OAK</u>	<u>6"</u>	<u>N47 E</u>	<u>15.10'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1972

Nov 2001 R. Mustonen #11946
Cert. of Svy. shows Mon. found

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____