


Index No. M 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

C/S 116 Corner common to sections 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
 Original monument 1x36" I.P. W/BRASS CAP S 116<sup>C</sup> 516 1918

Bearing Trees

Species	<u>J. PINE</u>	<u>J. PINE</u>	_____
Diameter	<u>6"</u>	<u>8"</u>	_____
Bearing	<u>S 10 1/4 E</u>	<u>S 87 3/4 W</u>	_____
Distance	<u>247 LKS</u>	<u>110 LKS</u>	_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman  
Set 2" x 1/2" galvanized steel pipe with brass cap.

Bearing Trees, Reference Objects

<u>N. PINE</u>	<u>J. PINE</u>
<u>20"</u>	<u>17"</u>
<u>S 13 W</u>	<u>N 80 W</u>
<u>142.30'</u>	<u>122.30'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate William Okerman 1974

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_