


Index No. M-N 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 57A Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C-5-5 164 Corner common to sections 16



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1918

Original monument 1x36" I.P. w/ BRASS CAP 516 | TR  
| 1675  
| AP3  
| AP2  
TR  
| 1674  
1918

**Bearing Trees**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search 1972 By William Okerman

Found GLO monument in good condition.

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Bearing Trees, Reference Objects**

<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>7"</u>	<u>7"</u>	<u>9"</u>
<u>S 24 W</u>	<u>N 74 W</u>	<u>N 12 W</u>
<u>22.50'</u>	<u>48.90'</u>	<u>35.30'</u>

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - BILL OKERMAN - 1972

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_