


T. 141 R. 28 M. 5th Coordinates: X _____ Y _____

MC# 2 Corner common to sections 13 24



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>ASH</u>	<u>BIRCH</u>	_____	_____
Diameter	<u>10"</u>	<u>6"</u>	_____	_____
Bearing	<u>S12W</u>	<u>N70W</u>	_____	_____
Distance	<u>24 LKS</u>	<u>60 LKS.</u>	_____	_____

Original Bearing Trees Found	_____	_____	_____	_____
Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
 Location filed SECRETARY OF STATE
 Monument ORIG. IN LAKE - SET 1x36" I.P. W/BRASS CAP.
714 IN
513 MC
574
R20W

Bearing Trees, Reference Objects 1918			
Species	<u>R. OAK</u>	<u>BIRCH</u>	_____
Diameter	<u>10"</u>	<u>12"</u>	_____
Bearing	<u>S86W</u>	<u>S41 3/4 W</u>	_____
Distance	<u>38 LKS</u>	<u>44 LKS</u>	_____

Evidence of Subsequent Corner Restoration

Year of search 1987 By Roger Mustonen
Corner Certificate - Doc # 362186
Find brass cap monument

Bearing Trees, Reference Objects			
<u>Ash</u>	<u>Maple</u>	<u>Maple</u>	<u>N/E CORNER</u>
<u>8"</u>	<u>5"</u>	<u>4"</u>	<u>Green cabin</u>
<u>N33 1/2 E</u>	<u>S59 1/2 E</u>	<u>S23 W</u>	<u>N56 1/2 W</u>
<u>16.64'</u>	<u>29.55'</u>	<u>4.10'</u>	<u>97'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Roger Mustonen - 1988