


Index No. N 23-24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
MC# 9 Corner common to sections 13, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>CEDAR</u>	<u>CEDAR</u>
Diameter <u>10"</u>	<u>9"</u>
Bearing <u>S 78 E</u>	<u>N 5 E</u>
Distance <u>15 LKS</u>	<u>57 LKS</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument SET 1x36" W/ BRASS CAP TYPIN
(ORIG. IN LAKE) MC / 513
524
R28W
1918

Evidence of Subsequent Corner Restoration

Year of search 1987 By Roger Mustonen
Corner Certificate - Doc # 302187
Find brass cap monument

Bearing Trees, Reference Objects	
Species <u>W. PINE</u>	<u>W. PINE</u>
Diameter <u>8"</u>	<u>12"</u>
Bearing <u>N 29 E</u>	<u>S 38 1/2 W</u>
Distance <u>74 LKS</u>	<u>270 LKS</u>

Bearing Trees, Reference Objects			
<u>W. Pine</u>	<u>Ash</u>	<u>Ash</u>	<u>Ash</u>
<u>19"</u>	<u>9"</u>	<u>7"</u>	<u>8"</u>
<u>N 29 E</u>	<u>NORTH</u>	<u>N 25 W</u>	<u>S 27 W</u>
<u>49.00'</u>	<u>1.70'</u>	<u>12.85'</u>	<u>24.32'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - MANDERS WILD ACRES
R.F. SCHNEIDER 1975

CERTIFICATE - BILL OKERMAN - 1973

Certificate - Roger Mustonen - 1988

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____