


Index No. Q7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 20 M. 5TH Coordinates: X _____ Y _____
C.S. 116 Corner common to sections 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1978
Original monument 1x36" 1/4" W BRASS CAP 5 1/16 9520
1978

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>J. PINE</u>	<u>J. PINE</u>	_____	_____
Diameter	<u>8"</u>	<u>10"</u>	_____	_____
Bearing	<u>N17 1/2 E</u>	<u>S54 1/2 E</u>	_____	_____
Distance	<u>13 LKS</u>	<u>102 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>J. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>
<u>10"</u>	<u>8"</u>	<u>7"</u>
<u>S 72 W</u>	<u>S 47 W</u>	<u>S 19 W</u>
<u>21.40'</u>	<u>27.10'</u>	<u>40.20'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____