


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed:  
Monument:  $1/4 \frac{S21}{S28}$   
1918

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed:  
Monument: \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed:  
Monument: \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found


Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed:  
Monument: \_\_\_\_\_

Index No. R 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 28 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

|          |                 |       |       |
|----------|-----------------|-------|-------|
| Species  | <u>N. PINE</u>  | _____ | _____ |
| Diameter | <u>14"</u>      | _____ | _____ |
| Bearing  | <u>N65E</u>     | _____ | _____ |
| Distance | <u>100 LKS.</u> | _____ | _____ |

Original Bearing Trees Found

|          |       |       |       |
|----------|-------|-------|-------|
| Species  | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed SECRETARY OF STATE  
Monument PROPORTIONAL POSITION SET 1/2 36" I.P.W./BRASS CAP  
1/4 521  
528  
1918

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

|          |                |                |       |
|----------|----------------|----------------|-------|
| Species  | <u>J. PINE</u> | <u>N. PINE</u> | _____ |
| Diameter | <u>10"</u>     | <u>10"</u>     | _____ |
| Bearing  | <u>S60°4E</u>  | <u>N4W</u>     | _____ |
| Distance | <u>170 LKS</u> | <u>282 LKS</u> | _____ |

Bearing Trees, Reference Objects

|          |               |                |                |
|----------|---------------|----------------|----------------|
| Species  | <u>Oak</u>    | <u>J. PINE</u> | <u>J. PINE</u> |
| Diameter | <u>10"</u>    | <u>14"</u>     | <u>12"</u>     |
| Bearing  | <u>N3E</u>    | <u>N14W</u>    | <u>S56W</u>    |
| Distance | <u>68.50'</u> | <u>59.90'</u>  | <u>133.90'</u> |

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1972

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_