


Index No. R 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 524 Coordinates: X _____ Y _____
N 14 27 Corner common to sections 22, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>POP LAR</u>	<u>OAK</u>	
<u>6"</u>	<u>12"</u>	
<u>N 63 E</u>	<u>51 E</u>	
<u>44 LKS</u>	<u>34 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument FIND OLD GOVT B.T: 24" W/OAK SIZE 34LKS,
SET 1X36" I.P. W/BRASS CAP 44-522
1918

Evidence of Subsequent Corner Restoration

Year of search 1971 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. OAK</u>	<u>10"</u>	<u>N 68 E</u>	<u>58 LKS</u>
<u>R. OAK</u>	<u>8"</u>	<u>S 23 1/2 W</u>	<u>47 LKS</u>

Bearing Trees, Reference Objects

R. Oak	W. Oak	W. Oak	R. Oak
<u>11"</u>	<u>9"</u>	<u>25"</u>	<u>17"</u>
<u>S 81 W</u>	<u>N 49 W</u>	<u>S 12 E</u>	<u>N 68 E</u>
<u>8.90'</u>	<u>41.00'</u>	<u>22.44'</u>	<u>38.30'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971

OCT 2003 M. Landecker # 7452
Cert. of Surv. shows Mon. Found

OCT 2004 T. Freeman # 21367
Cert. of Survey shows monument found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____