


Index No. 515

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.N. 116 Corner common to sections 27



○ = Corner

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1918  
 Original monument 1x36" (P.W.) BRASS CAP N 116 E 527  
 Bearing Trees 1918

Species <u>W. OAK</u>	Bearing <u>R. OAK</u>	Trees _____
Diameter <u>10"</u>	<u>14"</u>	_____
Bearing <u>N 20 1/4 E</u>	<u>N 81 3/4 W</u>	_____
Distance <u>39 LKS</u>	<u>3 LKS</u>	_____

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**  
 Year of search 1972 By William Oberman  
 Found GLO monument in good condition

**Bearing Trees, Reference Objects**

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

**Bearing Trees, Reference Objects**

<u>Oak</u>	<u>Oak</u>	<u>Oak</u>
<u>6"</u>	<u>7"</u>	<u>5"</u>
<u>N 52 W</u>	<u>S 30 E</u>	<u>S 41 W</u>
<u>66.20'</u>	<u>28.60'</u>	<u>35.30'</u>

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
1974 Certificate - William Oberman  
OCT 2003 M. Lendecker # 7452  
Cert. of Sup. Shows Mon. Found

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_