


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
MC # 5 Corner common to sections 26, 27



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument lost

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>
Diameter	<u>20"</u>	<u>20"</u>
Bearing	<u>N7E</u>	<u>N15W</u>
Distance	<u>38 LKS</u>	<u>42 LKS.</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

○ = Corner

Subsequent Corner Restoration
 Year surveyed 1918 By GLO
 Location filed SECRETARY OF STATE
 Monument NO ORIG. EVIDENCE - SET 1.896" IR. W/ BRASS CAP. TYPIN R28W 5271526 MS 1918

Evidence of Subsequent Corner Restoration
 Year of search 1988 By Gary Stevenson
Certificate - Doc # 303656
Found GLO monument

Bearing Trees, Reference Objects

Species	<u>W. OAK</u>	<u>W. OAK</u>
Diameter	<u>10"</u>	<u>8"</u>
Bearing	<u>N42E</u>	<u>N18 1/4 W</u>
Distance	<u>312 LKS</u>	<u>133 LKS</u>

Bearing Trees, Reference Objects

<u>Oak</u>	<u>Oak</u>	<u>Foundation</u>
<u>10" Twin</u>	<u>Triple 12"</u>	<u>SW Cor.</u>
<u>N20W</u>	<u>WEST</u>	<u>N50E</u>
<u>34.39</u>	<u>4.09'</u>	<u>59.40'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - LIKENS North Shore Beach
JOHN X STARK 1965
Certificate - Gary Stevenson - 1988
1989 Certificate - William Osufsen, RLS 17767
Doc # 310946
found 1918 GLO 1" x 3/8" iron pipe with brass cap. TIES: SE corner house
Foundation N62 W 35.65'; clump 12" OAK
N80 W 4.07'; SW corner house
Foundation N6 E 40.16'; SE corner
house foundation N 23 E 59.39'