


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 28 Corner common to sections 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>POPLAR</u>	<u>POPLAR</u>	
<u>4"</u>	<u>3"</u>	
<u>N 72 E</u>	<u>S 61 W</u>	
<u>30 LKS</u>	<u>34 LKS</u>	

Species	Bearing	Trees
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument PROPORTIONATE LOCATION - NO ORIG. EVIDENCE
SET 1 X 3/8" I.P. W/ BRASS CAP
1/4
528/527
1918

Evidence of Subsequent Corner Restoration

Year of search 1989 By David Landecker
Found GLO 1" iron monument with
brass cap.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. PINE</u>	<u>R. OAK</u>	
<u>12"</u>	<u>7"</u>	
<u>S 48 1/2 E</u>	<u>N 11 W</u>	
<u>27 LKS</u>	<u>19.5 LKS</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Birch</u>	<u>Burr Oak</u>	<u>Burr Oak</u>
<u>7"</u>	<u>6"</u>	<u>16"</u>
<u>North</u>	<u>N 34 E</u>	<u>S 81 E</u>
<u>40.44'</u>	<u>29.92'</u>	<u>77.26'</u>
		<u>17.8'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971
1989 Certificate - David Landecker
Doc. # 311160
Feb. 2004 T. Freeman # 21367
(cert. of Sur. Shows brass cap mon. found)

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____