


Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
N 1/4 36 Corner common to sections 25, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1874
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species CEDAR FIR
Diameter 6" 9"
Bearing S 85 W N 45 E
Distance 5 LKS 7 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1989 By David Landecker
Set 2" x 48" iron pipe with brass cap,
plastic base and magnet.

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
Balsam Ash Balsam
6" 5" 7"
N 80 W S 75 W S 5 E
38.20' 58.35' 55.36'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
1989 Certificate - David Landecker
Doc # 311944
1999 - Landecker & Assoc. - Survey info
indicates BC in place.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____