


T. 141 R. 28 M. 544 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SE 33 Corner common to sections 33, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>W. PINE</u>	<u>FIR</u>
Diameter <u>20"</u>	<u>6"</u>
Bearing <u>N27W</u>	<u>N50E</u>
Distance <u>8 LKS</u>	<u>12 LKS</u>

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURD  
Location filed COUNTY SURVEY RECORD BOOK "B" P. 265-269  
Monument SET CORNER PROPORTIONALLY

Evidence of Subsequent Corner Restoration

Year of search 1989 By DAVID LANDECKER  
Found 1 3/4" iron pipe  
Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

Bearing Trees, Reference Objects

Species <u>W. PINE</u>	<u>Maple</u>	_____
Diameter <u>STUMP</u>	<u>STUMP</u>	_____
Bearing <u>S10W</u>	<u>N80W</u>	_____
Distance <u>7.90'</u>	<u>10.25'</u>	_____

Bearing Trees, Reference Objects

Red Oak	Spruce	Birch
5"	5"	8"
N 40 W	N 8 W	N 16 E
42.27'	37.12'	61.53'

2-13

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - PINE GABLES OF THE NORTH  
JOHN M. GREENE 1928?  
1989 Certificate - David Landecker  
Doc # 312355

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_