


No. A 2-3

CASS COUNTY LAND CORNER RECORD

141 R. 29 M. 5TH Coordinates: X _____ Y _____
MC # 5B Corner common to sections 6 AND 31-142-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

| | Bearing | Trees |
|----------|---------------|------------------|
| Species | <u>W. OAK</u> | <u>W. OAK</u> |
| Diameter | <u>8"</u> | <u>8"</u> |
| Bearing | <u>N 24 W</u> | <u>S 50-30 E</u> |
| Distance | <u>21 LKS</u> | <u>18 LKS</u> |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SEC. OF STATE
Monument END BOTH CORN BITS NEW 12" SET 1X36"
I.P. w/ BRASS CAP.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects 7141-A
1918

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| | | | |
|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Plat - Rogers Peninsula
Garry Stevenson 1981

Remonumentation certificate prepared _____

By _____

dated at _____

Date _____