


Index No. D14

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
SW 1/4 Corner common to sections 3



O = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1918
Original monument 1x36" L.V. W/BRASS SW 1/4 53
CAP 1918

Year of search _____ By _____
Monument found _____

Species	Bearing Trees	
<u>R. OAK</u>	<u>W. OAK</u>	
Diameter <u>13"</u>	<u>10"</u>	
Bearing <u>S 86° E</u>	<u>N 58° 30' W</u>	
Distance <u>58 LKS</u>	<u>41 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By Landecker & Assoc.
Location filed CCSO
Monument Plat of Sugar Maple Shore Fifth
Add. indicates monument in place.

Year of search 5/2001 By CCSO
Found 1 1/4" OD IP, down 11', 7' E. of
& Diamond Point Road, 53' S. of &
Pursuit St.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>P. Pole</u>	<u>10"</u>	<u>N 65° E</u>	<u>46.13*</u>
<u>Maple</u>	<u>12"</u>	<u>N 15° W</u>	<u>77.87*</u>
<u>Maple</u>	<u>12"</u>	<u>N 15° W</u>	<u>77.87*</u>
			<u>26.60*</u>

*distance to double head nail

D-14

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____