


Index No. 02

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X 454161.98 Y 191853.40  
SW 1/16 Corner common to sections 6



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" IP.W/BRASS CAP SW 1/16 56  
1918

Original Evidence Found

Year of search 1/00 By USFS  
Monument found GLO brass cap

○ = Corner

Species	Bearing	Trees	Distance
<u>CEDAR</u>	<u>CEPAR</u>		
<u>7"</u>	<u>14"</u>		
<u>S68E</u>	<u>N25-30W</u>		
<u>9.45</u>	<u>36.45</u>		

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
<u>Cedar</u>	<u>3' 5 1/2"</u>	<u>N25°30'W</u>	<u>23.76'</u>
<u>New Ash</u>	<u>7 1/2"</u>	<u>S31°E</u>	<u>15.15'</u>
<u>New Cedar</u>	<u>5"</u>	<u>N65°E</u>	<u>47.10'</u>

Subsequent Corner Restoration

Year surveyed 9/03 By NLSEM  
Location filed USFS Cass Lake  
Monument Found GLO brass cap, topped  
replace with Alum cap rod monument  
2000 witnesses good. A C of L was  
filed.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects	Distance
<u>Ash</u>	<u>N38°W</u>	<u>5"</u>	<u>Steel post</u>	<u>29.96'</u>
	<u>N2°E</u>	<u>8'</u>	<u>Steel post</u>	<u>2.54'</u>
	<u>N89°W</u>	<u>8'</u>	<u>Steel post</u>	<u>2.81'</u>

Bearing Trees, Reference Objects

0-2

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remuneration certificate prepared #480064  
Filed at CCRO

By #16089  
Date 2/12/04