


T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 8 Corner common to sections 5, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species POPLAR OAK
Diameter 12" 15"
Bearing N80E S31E
Distance 37 LKS 35 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SEC. OF STATE
Monument FRS WOOD STAKE AND NE BIT STUMP SET
1x36" I.P. w/ BRASS CAP 14 55
58
1918

Evidence of Subsequent Corner Restoration

Year of search 1999 By Landecker & Assoc
Certificate of Survey indicates
Brass cap monument.

Bearing Trees, Reference Objects

Species W. OAK MAPLE
Diameter 6" 10"
Bearing S63-30W N73W
Distance 31 LKS 9 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BUTLER SMITH - HWY ENGINEER - PRJ
Found iron monument with brass cap. TIES:
8" OAK N 73° 30' W 60.5'; 10" OAK N 53 E
14.7'.