


Index No. H 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S116 Corner common to sections 1112



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1918 S116  
Original monument 1X36" I.P. w/ BRASS CAP S11 | S12  
1918

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Original Bearing Trees Found

Species POPULAR W. OAK \_\_\_\_\_  
Diameter 10" 6" \_\_\_\_\_  
Bearing S56°4'W S46°E \_\_\_\_\_  
Distance 29 LKS 98 LKS \_\_\_\_\_

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search 1986 By Roger Mustonen  
Set corner proportionally - fits w/ found  
15" W. oak SE 64.23' set 2" x 2 1/4" galv  
I.P. w/ brass cap. down 10"

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

R. oak W. oak Maple  
16" 15" 6"  
N51°E S59°E N66°W  
22.12' 64.23 21.36'  
(1918 660)

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Roger Mustonen - 1986  
Doc. # 289501