


Index No. H 8-9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

E-SE 1/4 Corner common to sections 8
A.P. # 1 1601, AP# 2 1603



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. w/BARS

TR 1570
TR 1601 | TR 1603
TR 1601 | TR 1603

Bearing Trees 1918

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1981 By Gary Stevenson
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Tamarack W. Oak
5" 9"
N 3/4 W N 7/8 E
17.45' 69.30'

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260984

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____