


Index No. J 14

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
W 1/4 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" 1/4 W/BASS W 1/4 510
CA 515
1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species POPLAR W/OAK
Diameter 5" 10"
Bearing S30-15E N47W
Distance 23 LKS 32 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1980 By Gary Stevenson
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>OAK stump</u>	<u>B. OAK</u>	<u>B. OAK</u>	<u>B. OAK</u>
<u>18"</u>	<u>9"</u>	<u>12"</u>	<u>7"</u>
<u>N 47 W</u>	<u>N 4 E</u>	<u>S 77 E</u>	<u>N 80 W</u>
<u>21.00'</u>	<u>28.61'</u>	<u>39.10'</u>	<u>14.63'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 200991

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____