


Index No. K7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" I.P. W/BASS N 1/16 1/2 517
CAD 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species SPRUCE ROAK
Diameter 7" 16"
Bearing S24E N24W
Distance 39 LKS 43 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1963 By PETE MEYER
Found G.I.O monument in good condition.
7" Spruce S24E 39 LKS now stub;
16" Red Oak N24W 43 LKS now 19"

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Maple Maple
6" 4"
S25W N87E
4.65' 18.9'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____